




State of Ohio Environmental Protection Agency

Northeast District Office

2110 E. Aurora Road
Twinsburg, Ohio 44087-1969
(216) 425-9171
FAX (216) 487-0769

EPA Region 5 Records Ctr.



200849

000005

George V. Voinovich
Governor

June 21, 1996

Mr. Thomas Alcamo
U.S. EPA Region V
77 West Jackson Blvd., HSRM-6J
Chicago IL 60604

Dear Mr. Alcamo:

I have enclosed some sampling results from the Master Metals site, as requested. I hope the information is helpful. If you have any additional questions, please feel free to call me at (216) 963-1206.

Sincerely,

Bart W. Ray
Division of Emergency and Remedial Response

BWR:ddb

enclosure



MASTER METALS

Summary of Samples

The following, in conjunction with the attached map, is a summary of sample results taken at the Master Metals Site in Cleveland, Ohio. The results were taken from Ohio EPA Divisions of Emergency And Remedial Response (DERR) and Hazardous Waste Management (DHWM). The list may not contain every sample taken at the site, just those located within OEPA Northeast District files. Note: Locations on map are estimates.

- A) Taken from the September monthly report as required in Consent Decree. Report is dated 10/15/90.
 - Furnace Brick - 112 ppm TCLP Pb
 - Sewer Sludge - 1210 ppm TCLP Pb, 16.8 ppm TCLP Cd
 - Plastic Battery Casings - 34.5 ppm TCLP Pb
- B) Soil sample taken by OSHA and reported to M. Bergman OEPA 2/90
 - Surface Soil - 2% Pb semi-quantitative result
- C) From Consent Decree monthly report dated 1/14/91
 - 129 drums of refractory brick - 6.8 ppm TCLP Pb (may not be on site at present)
- D) OEPA DHWM Samples (location unknown from file information) 4/6/92
 - Waste Pile #3 - 180 ppm TCLP Pb
- E) Fax fom Cuyahoga County Health Department to Linda Lagunzad DHWM 3/26/92 (locations unknown)
 - Silver Solid - 4600 ppm TCLP Pb
 - Soil Solids - 150 ppm TCLP Pb
- F) RECRA Environmental Results of 8/12/91 to Steve McBride OEPA, Columbus
 - S end of Rotary Furnace - 5340 ppm Pb (Total) - TCLP Non-Detect (nd)
 - Bin #7 - 1170 ppm Pb (Total) - TCLP- nd
 - Bin #5 - 4870 ppm Pb (Total) - TCLP - nd
- G) CTI Consultants sampling results dated 12/28/90
 - Borings noted on map as B-1, B-2, B-3.....B-31
 - Results attached

